


C30A Encounter Overview



Note: Two Bus Reset PORs occurred during the encounter time period, both of which were properly handled by the on-board recovery routine.
The times were: 01-143/15:49:08 SCET and 01-144/04:34:19 SCET.
SSI Power cycle and fast reloads were sent at 01-143/21:30:00 TRM and 01-144/16:25:00 TRM.

BMCL/SST
06/06/01